


October 2011 Progress Photos
Moore's Creek WWTTP ENR Upgrade



Secondary Clarifier No. 3 – Placement of Grout Floor



Interior of Secondary Clarifier No. 3



Secondary Clarifier No. 4 in Operation



Grading and Stakeout for New Stormwater and Curb in the Maintenance Yard



Stormwater Piping Installation – Maintenance Yard



Stormwater Installation – Maintenance Yard



New Maintenance Building Drain Trench Installation



Subgrade for Curb near Secondary Clarifier No. 4



Holding Pond Line Flow – Metering Vault



North Side Paving near the UV Facility



North Side Paving near Boiler and Filter Facilities



North Side Paving near Digester Complex



North Side Paving near the UV Facility and Backwash Tanks



North Side Paving near Solids Handling Facility